CREW	192 WORK ORDER TYPE: MODIFICATIONS		03-96033-9	ISSUE DATE 01/06/11	Page 1 Of	2	
	nator : JERRY FINLINSON Schedule Date er : JIMMIE KNAPP Priority	: : : 3A		Date Completed:	Failure	Code:	
	ng No : 2SGE-M2067 Clearance	: NO		Completed By :	Signatur	e :	
Proj	No/Cat: 2SGE0 3 Tag Request ct ID : 2SGE-ACC-1A Text ID	; ;	MIDDIN ED	Accepted By :	Signatur	e :	
Shute Ref I	o : Last Reading		ading		W=Whse C=CrSp ** Record Ti	•	P=Plan Delays
Step	Job Scope	MN DY	Safety and Additional		Emp No Date	Hours	Code/Hrs
1	REMOVE THE TEMPERATURE SWITCHES FROM ALL BURNERS AFTER THE UNIT IS SHUT DOWN. REINSTALL AT STARTUP 0707.051 (X48) ***********************************		**************************************	REQUIREMENTS: DF THE CONSTRUCTION HIS AREA. REWITCHES WILL BE OUTAGE IN THE SAME	** IMPORT YOU ARE RESPONSIBLE ENSURE THAT THE REQ	ANT NOTICE ** FOR YOUR OWN SAFET	TY AND MUST
2	ADDITIONAL TIME ADDED FOR THE FOLLOWING:	1 1				UIRED PPE IS WORN F IF YOU HAVE ANY QU RULES, SAFETY CODE	FOR EVERY JESTIONS ES, OR

Job Feedback/Historical Notes:

IP7_032288



CREW: 192 WORK ORDER TYPE: MODIFICATIONS 03-96033-9 ISSUE DATE 01/06/11 Page 2 Of 2

** Work Order Parts List **

	Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
1	08050	WIRE (ELECT), THHN	S 280418	04/03/04	RL	1	0	1
2	13724	WIRE (ELECT), THHN	S 280418	04/03/04	RL	1	0	1
3	19668	WIRE (ELECT), THHN	S 280634	04/06/04	RL	1	0	1
4	50170	NUT, WIRE	S 280397	04/03/04	EA	100	0	100
5	68483	SWITCH, TEMPERATURE	S 281080	04/08/04	EA	1	0	1

IP7_032289